# **HOME REPORT**

FLAT 1 34 SPEIRS WHARF GLASGOW G4 9TG



# ENERGY PERFORMANCE CERTIFICATE



## **Energy Performance Certificate (EPC)**

**Dwellings** 

# **Scotland**

#### FLAT 1, 34 SPEIRS WHARF, GLASGOW, G4 9TG

Dwelling type: Mid-floor flat
Date of assessment: 12 February 2020
Date of certificate: 13 February 2020

Total floor area: 122 m<sup>2</sup>

Primary Energy Indicator: 379 kWh/m²/year

**Reference number:** 2210-1522-9000-0222-0296 **Type of assessment:** RdSAP, existing dwelling

**Approved Organisation:** Elmhurst


Main heating and fuel: Electric storage heaters

#### You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO<sub>2</sub> emissions by improving your home

| Estimated energy costs for your home for 3 years* | £4,833 | See your recommendations    |
|---|--------|-----------------------------|
| Over 3 years you could save*                      | £1,326 | report for more information |

<sup>\*</sup> based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




#### **Energy Efficiency Rating**

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (62)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



#### **Environmental Impact (CO<sub>2</sub>) Rating**

This graph shows the effect of your home on the environment in terms of carbon dioxide  $(CO_2)$  emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band E (42)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

#### Top actions you can take to save money and make your home more efficient

| Recommended measures                   | Indicative cost  | Typical savings over 3 years |
|--|------------------|------------------------------|
| 1 Internal or external wall insulation | £4,000 - £14,000 | £615.00                      |
| 2 High heat retention storage heaters  | £1,600 - £2,400  | £711.00                      |

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

#### Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

| Element               | Description   | Energy Efficiency | Environmental |
|-----------------------|---|-------------------|---------------|
| Walls                 | Sandstone or limestone, as built, no insulation (assumed) | ***               | ***           |
|                       | Solid brick, as built, partial insulation (assumed)       | ★★★☆☆             | <b>★★★☆☆</b>  |
| Roof                  | (another dwelling above)                                  | _                 | _             |
| Floor                 | (other premises below)                                    | _                 | _             |
| Windows               | Fully double glazed                                       | ★★★☆☆             | ***           |
| Main heating          | Electric storage heaters                                  | ★★★☆☆             | ****          |
| Main heating controls | Manual charge control                                     | ***               | ***           |
| Secondary heating     | Room heaters, electric                                    | _                 | _             |
| Hot water             | Electric immersion, off-peak                              | <b>★★★☆☆</b>      | ***           |
| Lighting              | Low energy lighting in all fixed outlets                  | ****              | ****          |

#### The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

#### The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 64 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 7.8 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.9 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

#### Estimated energy costs for this home

|           | Current energy costs | Potential energy costs | Potential future savings |
|-----------|----------------------|------------------------|--------------------------|
| Heating   | £3,882 over 3 years  | £2,556 over 3 years    |                          |
| Hot water | £648 over 3 years    | £648 over 3 years      | You could                |
| Lighting  | £303 over 3 years    | £303 over 3 years      | save £1,326              |
| Total     | s £4,833             | £3,507                 | over 3 years             |

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

#### Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.


| Da | commanded massives                   | Indiantive and   | Typical saving | ical saving Rating after |             |
|----|--------------------------------------|------------------|----------------|--------------------------|-------------|
| Re | commended measures                   | Indicative cost  | per year       | Energy                   | Environment |
| 1  | Internal or external wall insulation | £4,000 - £14,000 | £205           | D 67                     | E 48        |
| 2  | High heat retention storage heaters  | £1,600 - £2,400  | £237           | C 73                     | E 54        |

#### **Alternative measures**

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

- Biomass boiler (Exempted Appliance if in Smoke Control Area)
- Air or ground source heat pump

#### Choosing the right improvement package





#### About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

#### 1 Internal or external wall insulation

Internal or external wall insulation involves adding a layer of insulation to either the inside or the outside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. External solid wall insulation is the application of an insulant and a weather-protective finish to the outside of the wall. This may improve the look of the home, particularly where existing brickwork or rendering is poor, and will provide long-lasting weather protection. Further information can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). It should be noted that a building warrant is required for the installation of external wall insulation. Planning permission may also be required and that building regulations apply to external insulation so it is best to check with your local authority on both issues.

#### 2 High heat retention storage heaters

Modern storage heaters have better insulation and are easier to control than the older type in this property. Ask for a quotation for new, high heat retention heaters with automatic charge and output controls. Installations should be in accordance with the current regulations covering electrical wiring. Ask the heating engineer to explain the options, which might also include switching to other forms of electric heating.

#### Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

**LZC energy sources present:** There are none provided for this home

#### Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

| Heat demand                  | Existing dwelling | Impact of loft insulation | Impact of cavity wall insulation | Impact of solid wall insulation |
|------------------------------|-------------------|---------------------------|----------------------------------|---------------------------------|
| Space heating (kWh per year) | 12,383            | N/A                       | N/A                              | (1,970)                         |
| Water heating (kWh per year) | 2,179             |                           |                                  |                                 |

#### **Addendum**

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

#### **About this document**

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Alan Cunningham

Assessor membership number: EES/009362

Company name/trading name: D M Hall Chartered Surveyors LLP

Address: 151/153 Kilmarnock Road

Glasgow Shawlands G41 3JE

Phone number: 0141 636 4141

Email address: enquiries@dmhall.co.uk

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

#### Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

#### Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greeners cotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT



# SINGLE SURVEY



# survey report on:

| Property address    FLAT 1 34 SPEIRS WHARF GLASGOW G4 9TG                         |                    |                            |
|---|--------------------|----------------------------|
| Customer address  Flat 1 34 Speirs Wharf Glasgow G4 9TG  Prepared by  DM Hall LLP | Property address   | 34 SPEIRS WHARF<br>GLASGOW |
| Customer address  Flat 1 34 Speirs Wharf Glasgow G4 9TG  Prepared by  DM Hall LLP |                    |                            |
| 34 Speirs Wharf Glasgow G4 9TG  Prepared by  DM Hall LLP                          | Customer           | Miss Emily Allan           |
| 34 Speirs Wharf Glasgow G4 9TG  Prepared by  DM Hall LLP                          |                    |                            |
|   | Customer address   | 34 Speirs Wharf<br>Glasgow |
|   |                    |                            |
| Date of inspection 12th February 2020   | Prepared by        | DM Hall LLP                |
| Date of inspection 12th February 2020   |                    |                            |
|   | Date of inspection | 12th February 2020         |



#### PART 1 - GENERAL

#### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property<sup>1</sup>.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

#### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in the expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

<sup>&</sup>lt;sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

#### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:-

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### 1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

#### 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report <sup>2</sup> will be from information contained in the Report and the generic Mortgage Valuation Report.

<sup>&</sup>lt;sup>2</sup>Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

#### 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

#### 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

#### 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

#### 1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller:
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

#### PART 2 - DESCRIPTION OF THE REPORT

#### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

#### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

#### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2. Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3. Category 1: No immediate action or repair is needed.

#### **WARNING:**

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

#### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

#### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

#### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

#### 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value, the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

#### 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

| Description                    | Second Floor left most flat conversion set within a former warehouse building which is Category B listed as of architectural / historical interest. The building is six storeys in height with self contained commercial premises on the lower floors. The flat contains approximately 16 flats with lift access to all floors. In addition there is a shared stairwell. |
|--------------------------------|--|
| _                              |  |
| Accommodation                  | Second Floor: Entrance Hall, Living Room open plan to Dining Room and Breakfasting sized Kitchen, three Bedrooms with Master having en-suite Shower Room and Family Bathroom.  |
|                                |  |
| Gross internal floor area (m²) | Approximately 122 square metres.   |
|                                |  |
| Neighbourhood and location     | The subjects are situated on the western side of Craighall Road overlooking a stretch of the Forth and Clyde Canal in the Port Dundas district of Glasgow, a mixed residential / commercial / industrial area, a short distance to the north of Glasgow's city centre. The surrounding area comprises a variety of property types. Convenient by car to local amenities. |
|                                |  |
| Age                            | Built circa 1860. The former Grain Store was converted to residential / commercial usage in circa 1991.  |
|                                |  |
| Weather                        | Overcast with sleet showers at the time of inspection. A period of mixed weather preceded my visit.  |
|                                |  |
| Chimney stacks                 | Visually inspected with the aid of binoculars where appropriate.   |
|                                | No chimney stacks.   |
|                                |  |

#### Roofing including roof space Sloping roofs were visually inspected with the aid of binoculars where appropriate. Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally. Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so. The roof is timber pitched and clad with natural slates. There is no readily available access to the communal roof space. Rainwater fittings Visually inspected with the aid of binoculars where appropriate. Gutters are of concealed wallhead type lined with lead or similar (not seen). Downpipes are of cast iron sections with cast iron hopper features. Main walls Visually inspected with the aid of binoculars where appropriate. Foundations and concealed parts were not exposed or inspected. Solid sandstone / brick wall construction having a pointed stone external finish with steel features . There are steel column features as part of the original steel internal framework. The damp proof course is not visible and assumed to be of a slate or modern equivalent. Windows, external doors and joinery Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. Windows: Double glazed timber framed units throughout. External Doors: The subject flat is entered from the shared landing through a timber panelled door.

Joinery: External joinery is of timber.

| External decorations               | Visually inspected.  |
|------------------------------------|--|
|                                    | Painted timber features.   |
|                                    | Fairted timber reatures.   |
| Conservatories / porches           | Visually inspected.  |
|                                    | No conservatories or porches.  |
| Communal areas                     | Circulation areas visually inspected.  |
|                                    | Shared entrance hall / stairwell having a glass timber panelled entrance door with security entry system attached. The entrance foyer has a concrete floor covered with carpet, pointed brick walls and a painted textured ceiling. The stairwell has painted textured ceiling and wall linings. The Second Floor shared landing has a carpet floor finish and plasterboard ceiling and wall linings. Daylighting is provided by double glazed timber framed windows.  There is a lift access to all floors. |
|                                    | T  |
| Garages and permanent outbuildings | Visually inspected.  No garage or garage space. Unallocated residents car parking adjacent to the building surfaced with cobbles or monoblock. No permanent outbuildings.  |
| Outside areas and boundaries       | Visually inspected.  |
|                                    | No garden grounds. The building is adjacent to a canal basin.  |
|                                    |  |
| Ceilings                           | Visually inspected from floor level.   |
|                                    | Plasterboard design.   |
| Internal walls                     | Visually inspected from floor level.   |
|                                    | Using a moisture meter, walls were randomly tested for dampness where considered appropriate.  |
|                                    | Timber stud lined with plasterboard.   |
| Floors including sub floors        | Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.  Sub-floor areas were inspected only to the extent visible from   |
|                                    | Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.   |
|                                    | Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.   |
|                                    | Appears of solid concrete supporting timber battens and compressed chipboard panels. Floors are covered with wood  |

|                                       | overlay, carpet, vinyl or tiles.  |
|---------------------------------------|---|
|                                       |   |
| Internal joinery and kitchen fittings | Built-in cupboards were looked into but no stored items were moved.  Kitchen units were visually inspected excluding appliances.  Internal joinery is of timber. Interior doors are timber panelled units. The Kitchen is open plan to the Reception Room and comprises work surfaces and a range of floor and wall mounted units. The Kitchen has a stainless steel sink unit with drainer, electric hob and central work station / breakfast bar feature. |
| Chimney breasts and fireplaces        | Visually inspected.   |
|                                       | No testing of the flues or fittings was carried out.  |
|                                       |   |
|                                       | No chimney breasts or fireplaces.   |
| Internal decorations                  | Visually inspected.   |
| internal decorations                  | Predominantly painted ceiling and wall surfaces. Tile splashback to kitchen work surfaces. Wall panelled features in Bathroom. Fully wall tiled en-suite Shower Room.   |
| Cellars                               | Visually inspected where there was a safe and purpose-built access.   |
|                                       | No cellar.  |
| Electricity                           | Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.  Main supply with the meter and switch gear in the hall cupboard.       |
| Gas                                   | Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.  No mains gas supply connected.   |

| Water, plumbing, bathroom fittings                                  | Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.  |
|---|---|
|   | No tests whatsoever were carried out to the system or appliances.   |
|   | Main supply. The Bathroom having no natural light is mechanically ventilated and comprises a white low level WC, wash hand basin, panel bath and separate shower cubicle. Similarly the en- suite Shower Room having no natural light is mechanically ventilated and comprises a white low level WC, wash hand basin and shower cubicle.  |
| Heating and hot water   | Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.   |
|   | No tests whatsoever were carried out to the system or appliances.   |
|   | Electric storage / panel heating in main apartments. There is an electric towel rail in en-suite facility. Hot water is provided by an insulated hot water cylinder with electric emersion heater attached.   |
| Drainage  | Drainage covers etc. were not lifted.   |
|   | Neither drains nor drainage systems were tested.  |
|   | Assumed connected to the main public sewerage system.   |
|   |   |
| Fire, smoke and burglar alarms                                      | Visually inspected.   |
| Fire, smoke and burglar alarms                                      | Visually inspected.  No tests whatsoever were carried out to the system or appliances.  |
| Fire, smoke and burglar alarms                                      | No tests whatsoever were carried out to the system or   |
| Fire, smoke and burglar alarms  Any additional limits to inspection | No tests whatsoever were carried out to the system or appliances.   |
|   | No tests whatsoever were carried out to the system or appliances.  Smoke detector and fire alarm systems in place.  |
|   | No tests whatsoever were carried out to the system or appliances.  Smoke detector and fire alarm systems in place.  For flats / maisonettes  Only the subject flat and internal communal areas giving   |
|   | No tests whatsoever were carried out to the system or appliances.  Smoke detector and fire alarm systems in place.  For flats / maisonettes  Only the subject flat and internal communal areas giving access to the flat were inspected.  If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no  |
|   | No tests whatsoever were carried out to the system or appliances.  Smoke detector and fire alarm systems in place.  For flats / maisonettes  Only the subject flat and internal communal areas giving access to the flat were inspected.  If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.  The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general |


roof void areas available for inspection. As a result of site constraints and the presence of surrounding buildings and canal only a limited Ground Level inspection of the roof covering impertinence is feasible.

Parts of the property, which are covered, unexposed or inaccessible, cannot be guaranteed to be free from defect.

I have not carried out an inspection for Japanese Knotweed and unless otherwise stated, for the purposes of the valuation I have assumed that there is no Japanese Knotweed or other invasive plants within the boundaries of the property or in neighbouring properties.

The report does not include an asbestos inspection. However asbestos was widely used in the building industry until around 2000, when it became a banned substance. If the possibility of asbestos based products has been reported within the limitations of the inspection and you have concerns you should engage a qualified asbestos surveyor.

#### Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1) Chimney pots
- (2) Coping stone
- 3) Chimney head
- 4) Flashing
- (5) Ridge ventilation
- 6) Ridge board
- 7) Slates / tiles
- (8) Valley guttering
- 9) Dormer projection
- 10 Dormer flashing
- 11) Dormer cheeks
- (12) Sarking
- (13) Roof felt
- (14) Trusses
- 15) Collar
- (16) Insulation
- 7) Parapet gutter
- 18) Eaves guttering
- 19) Rainwater downpipe
- 0) Verge boards /skews
- 21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- Latin / plaster
- (24) Chimney breast
- 25) Window pointing
- 26) Window sills
- (27) Rendering
- (28) Brickwork / pointing
- 29) Bay window projection
- (30) Lintels
- (31) Cavity walls / wall ties
- 32) Subfloor ventilator
- 33) Damp proof course
- 34) Base course
- 35) Foundations
- 36) Solum
- 37) Floor joists
- 38) Floorboards
- 9) Water tank
- 10) Hot water tank

#### 2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

| Category 3 | Category 2  | Category 1 |
|------------|---|------------|
|            | Repairs or replacement requiring future attention, but estimates are still advised. |            |

| Structural movemen | nt  |
|--------------------|---|
| Repair category    | 1   |
| Notes              | The property has been affected by previous movement but within the limitations of the inspection there was no evidence to suggest that this is ongoing. |

| Dampness, rot and infestation |  |
|-------------------------------|--|
| Repair category               | 1  |
| Notes                         | No obvious evidence of significant dampness, rot or wood boring insect infestation |

| Chimney stacks  |       |
|-----------------|-------|
| Repair category | -     |
| Notes           | None. |

| Roofing including roof space |   |
|------------------------------|---|
| Repair category              | 2   |
| Notes                        | Affected by general ageing and weathering. Given the exposed location ongoing careful common maintenance is envisaged. A reputable roofing contractor can be asked to inspect the roof structure to advise on all necessary common repairs to ensure durability. Regular common maintenance and potentially future replacement are likely |

| Rainwater fittings |  |
|--------------------|--|
| Repair category    | 2  |
| Notes              | There are wall head gutters. These can be problematic, especially within older buildings, and maintenance should be undertaken regularly.  Cast iron sections are corroded to varying degrees. |

| Main walls      |   |
|-----------------|---|
| Repair category | 2   |
| Notes           | Affected by general ageing and weathering with eroded stonework particularly on the front elevation. Vegetation is noted to some stone ledges at the front. |

| Windows, external doors and joinery |  |
|-------------------------------------|--|
| Repair category                     | 2  |
| Notes                               | Window units are dated and weathered. Units are paint sealed. Misting is evident indicative of blown double glazed sealed units. |

| External decorations |  |
|----------------------|--|
| Repair category      | 1                                      |
| Notes                | There is weathered external paintwork. |

| Conservatories/porches |       |
|------------------------|-------|
| Repair category        | -     |
| Notes                  | None. |

| Communal areas  |   |
|-----------------|---|
| Repair category | 1   |
| Notes           | Affected by wear and tear.  There are textured finishes to some ceiling surfaces. See information on Asbestos in the Limitations of Inspection section above. |

| Origic Garvey                         |  |  |
|---------------------------------------|--|--|
| Garages and permanent outbuildings    |  |  |
| Repair category                       | -  |  |
| Notes                                 | None.  |  |
| Outside areas a                       | nd boundaries  |  |
| Repair category                       | 1  |  |
| Notes                                 | No significant defects evident.  |  |
| Ceilings                              |  |  |
| Repair category                       | 1  |  |
| Notes                                 | The textured finishes may contain asbestos based material. See information on Asbestos in the Limitations of Inspection section above. |  |
| Internal walls                        |  |  |
| Repair category                       | 1  |  |
| Notes                                 | No significant defects evident.  |  |
| Floors including sub-floors           |  |  |
| Repair category                       | 1  |  |
| Notes                                 | No visual defects.   |  |
| Internal joinery and kitchen fittings |  |  |
| Repair category                       | 1  |  |
| Notes                                 | No significant defects evident.  |  |
|                                       |  |  |

Repair category

**Notes** 

**Chimney breasts and fireplaces** 

None.

| Internal decorations |                                 |
|----------------------|---------------------------------|
| Repair category      | 1                               |
| Notes                | No significant defects evident. |

| Cellars         |       |
|-----------------|-------|
| Repair category | -     |
| Notes           | None. |

| Electricity     |   |
|-----------------|---|
| Repair category | 1   |
| Notes           | No visual defects. It is recommended that all electrical installations be checked every five years or on change of ownership to keep up to date with frequent changes in Safety Regulations. Further advice will be available from a qualified NICEIC/ SELECT registered Contractor. It should be appreciated that only recently constructed or rewired properties will have installations which fully comply with IEE regulations. |

| Gas             |               |
|-----------------|---------------|
| Repair category | -             |
| Notes           | No mains gas. |

| Water, plumbing and bathroom fittings  |  |
|--|--|
| Repair category 1  |  |
| No visual defects. Seals around bath / shower areas are frequently trouble Failure to seals can result in dampness / decay to concealed underlying a |  |

| Heating and hot water |   |
|-----------------------|---|
| Repair category       | 1   |
| Notes                 | No visual defects.  It is assumed that the heating and hot water systems have been properly serviced and maintained on a regular basis and installed in accordance with the relevant regulations. |

| Drainage        |                                 |
|-----------------|---------------------------------|
| Repair category | 1                               |
| Notes           | No significant defects evident. |

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

| Structural movement                   | 1 |
|---------------------------------------|---|
| Dampness, rot and infestation         | 1 |
| Chimney stacks                        | - |
| Roofing including roof space          | 2 |
| Rainwater fittings                    | 2 |
| Main walls                            | 2 |
| Windows, external doors and joinery   | 2 |
| External decorations                  | 1 |
| Conservatories/porches                | - |
| Communal areas                        | 1 |
| Garages and permanent outbuildings    | - |
| Outside areas and boundaries          | 1 |
| Ceilings                              | 1 |
| Internal walls                        | 1 |
| Floors including sub-floors           | 1 |
| Internal joinery and kitchen fittings | 1 |
| Chimney breasts and fireplaces        | - |
| Internal decorations                  | 1 |
| Cellars                               | - |
| Electricity                           | 1 |
| Gas                                   | - |
| Water, plumbing and bathroom fittings | 1 |
| Heating and hot water                 | 1 |
| Drainage                              | 1 |

#### **Category 3**

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

#### Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

#### Category 1

No immediate action or repair is needed.

#### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

#### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

#### 3. Accessibility information

#### Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

#### Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

| 1. Which floor(s) is the living accommodation on?                                      | Second   |
|--|----------|
| 2. Are there three steps or fewer to a main entrance door of the property?             | Yes X No |
| 3. Is there a lift to the main entrance door of the property?                          | Yes X No |
| 4. Are all door openings greater than 750mm?   | Yes X No |
| 5. Is there a toilet on the same level as the living room and kitchen?                 | Yes X No |
| 6. Is there a toilet on the same level as a bedroom?                                   | Yes X No |
| 7. Are all rooms on the same level with no internal steps or stairs?                   | Yes X No |
| 8. Is there unrestricted parking within 25 metres of an entrance door to the building? | Yes X No |

#### 4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

#### Matters for a solicitor or licensed conveyancer

It is assumed that a factor is appointed to the building and that maintenance and repairing liabilities are in order. Enquiries should be made to ascertain whether any common repairs or planned proposed or contemplated which may affect the subjects.

The flat may have a common building reinstatement policy administered by the factor.

The subjects form part of a tenement/block of flats and it has been assumed that maintenance/repair costs of the common parts of the building will be shared on an equitable basis with adjoining proprietors. It is therefore assumed that the cost of common repairs detailed within the report will be apportioned accordingly although exact liability should be confirmed. (insert when property in a block of flats)

There are common facilities pertaining to the development including swimming pool and leisure facilities. Legal advisors to verify.

The parking provision and status of the access road should be checked and verified by legal advisors. The property fronts onto a stretch of the Forth and Clyde Canal. It is assumed that there are no onerous liabilities.

The property is Category B Listed as of architectural / historical interest. As a result the cost of repair or reinstatement works are likely to be higher than normal. Any works considered necessary will require to be carried out in consultation with the Local Planning Authority and Historic Scotland.

With regard to the formation of the subject flat in its current layout, it is assumed that all necessary Local Authority and other consents have been obtained and the appropriate documentation is in place.

#### Estimated reinstatement cost for insurance purposes

£420,000 (FOUR HUNDRED AND TWENTY THOUSAND POUNDS).

It should be noted this sum is an estimate calculated by using a rate per square metre based on information provided by Building Cost Information Service (BCIS).

For Listed buildings and historic properties within Conservation Areas you should seek further specialist insurance advice.

#### Valuation and market comments

£250,000 (TWO HUNDRED AND FIFTY THOUSAND POUNDS)

| Security Print Code [580287 = 7152 ] Electronically signed |
|--|
|  |

| Report author | Alan E Cunningham |
|---------------|-------------------|
|---------------|-------------------|

| Company name   | DM Hall LLP                           |
|----------------|---------------------------------------|
| Address        | 151 Kilmarnock Road, Glasgow, G41 3JF |
| Date of report | 14th February 2020                    |

# Mortgage Valuation Report



| Property Address  |   |  |
|---|---|--|
| Address<br>Seller's Name<br>Date of Inspection  | FLAT 1, 34 SPEIRS WHARF, GLASGOW, G4 9TG<br>Miss Emily Allan<br>12th February 2020  |  |
| Property Details  |   |  |
| Property Type   | ☐ House       ☐ Bungalow       ☐ Purpose built maisonette       ☐ Converted maisonette         ☐ Purpose built flat       X Converted flat       ☐ Tenement flat       ☐ Flat over non-residential use         ☐ Other (specify in General Remarks) |  |
| Property Style  | □ Detached       □ Semi detached       □ Mid terrace       □ End terrace         □ Back to back       □ Semi detached       □ Low rise block       □ Other (specify in General Remarks)   |  |
| Does the surveyor believe that the property was built for the public sector,                |   |  |
| Flats/Maisonettes onl<br>Approximate Year of  | No. of units in block 16  |  |
| Tenure  |   |  |
| X Absolute Ownership  | Leasehold Ground rent £ Unexpired years   |  |
| Accommodation   |   |  |
| Number of Rooms   | 1 Living room(s) 3 Bedroom(s) 1 Kitchen(s) 2 Bathroom(s) 2 WC(s) 0 Other (Specify in General remarks)   |  |
| Gross Floor Area (excluding garages and outbuildings)  122 m² (Internal)  140 m² (External) |   |  |
| Residential Element (   | (greater than 40%) X Yes No   |  |
| Garage / Parking /  | Outbuildings  |  |
| Single garage Available on site?  | □ Double garage       X Parking space       □ No garage / garage space / parking space         X Yes       No   |  |
| Permanent outbuildin  | ngs:  |  |
| None of significance  | 9.  |  |

## Mortgage Valuation Report

| Construction                                |                 |                     |                       |                           |                |                    |                |
|---|-----------------|---------------------|-----------------------|---------------------------|----------------|--------------------|----------------|
| Walls                                       | Brick           | X Stone             | Concrete              | Timber frame              | Other          | r (specify in Gen  | eral Remarks)  |
| Roof  | Tile            | X Slate             | Asphalt               | Felt                      | Other          | r (specify in Gen  | eral Remarks)  |
| Special Risks                               |                 |                     |                       |                           |                |                    |                |
| Has the property s                          | suffered struc  | tural moveme        | ent?                  |                           |                | X Yes              | No             |
| If Yes, is this rece                        | nt or progress  | sive?               |                       |                           |                | Yes                | X No           |
| Is there evidence, immediate vicinity       |                 | ason to antic       | ipate subsidence      | , heave, landslip o       | r flood in the | Yes                | X No           |
| If Yes to any of the                        | e above, prov   | ide details in      | General Remark        | ss.                       |                |                    |                |
| Service Connec                              | tions           |                     |                       |                           |                |                    |                |
| Based on visual ir of the supply in G       |                 |                     | ices appear to be     | e non-mains, pleas        | e comment (    | on the type a      | nd location    |
| Drainage                                    | X Mains         | Private             | None                  | Water                     | X Mains        | Private            | None           |
| Electricity                                 | X Mains         | Private             | None                  | Gas                       | Mains          | Private            | X None         |
| Central Heating                             | Yes             | Partial             | X None                |                           |                |                    |                |
| Brief description o                         | f Central Hea   | ting:               |                       |                           |                |                    |                |
| No central heatir                           | ng. Electric st | orage/panel         | heating.              |                           |                |                    |                |
| Site  |                 |                     |                       |                           |                |                    |                |
| Apparent legal iss                          | ues to be ver   | ified by the c      | onveyancer. Ple       | ase provide a brief       | description    | in General R       | emarks.        |
| Rights of way                               | X Shared driv   | •                   |                       | amenities on separate     | Ċ              | red service conn   |                |
| Ill-defined boundar                         | ies             | Agricul             | tural land included w | th property               | Othe           | er (specify in Ger | neral Remarks) |
| Location                                    |                 |                     |                       |                           |                |                    |                |
| Residential suburb                          | X Res           | sidential within to | own / city Mixe       | ed residential / commerce | cial Main      | nly commercial     |                |
| Commuter village                            | Rei             | mote village        | Isola                 | ated rural property       | Othe           | er (specify in Ger | neral Remarks) |
| Planning Issues                             | 5               |                     |                       |                           |                |                    |                |
| Has the property but If Yes provide details |                 |                     | / altered? X          | Yes No                    |                |                    |                |
| Roads                                       |                 |                     |                       |                           |                |                    |                |
| X Made up road                              | Unmade roa      | d Partly            | completed new road    | Pedestrian ad             | ccess only     | Adopted            | Unadopted      |

## Mortgage Valuation Report

| General Remarks   |
|---|
| Overall, the subjects were found to be in generally satisfactory condition having regard to its age, type and construction with no obvious significant defects evident which would adversely affect security or value.                                    |
| The subject flat is well presented having been upgraded on relatively recent times. Window units are dated and weathered. Common maintenance repairs are needed to the external building fabric.  |
| The movement is considered long standing and non progressive.   |
| It is assumed that a factor is appointed to the building and that maintenance and repairing liabilities are in order. Enquiries should be made to ascertain whether any common repairs or planned proposed or contemplated which may affect the subjects. |
| At the time of inspection, the subjects were unoccupied, furnished and floors covered. There is lift access to all floors.  |
|   |
|   |
|   |
| Eccential Panaire   |
| Essential Repairs   |
| None apparent.  |
| ·   |
| ·   |
| ·   |
| ·   |
| ·   |
| ·   |
| ·   |
| ·   |
| ·   |
| •   |

Retention recommended? Yes X No

Estimated cost of essential repairs £ \_\_\_\_

Amount £

### Mortgage Valuation Report

| Comment on Mortgageability |
|----------------------------|
|----------------------------|

We confirm the subjects form suitable security for mortgage purposes at the stated level of value and subject to individual lender's criteria.

The subjects are positioned above commercial premises. Some lenders are reluctant to grant mortgage facilities on flats positioned above non-residential uses. Further advice may be necessary.

#### **Valuations**

Market value in present condition

£ 250,000

Market value on completion of essential repairs

£ 420,000

Insurance reinstatement value

(to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)

Is a reinspection necessary?

Yes X No

#### **Buy To Let Cases**

What is the reasonable range of monthly rental income for the property assuming a letting on a 6 month Short Assured Tenancy basis?

| £ |  |
|---|--|
|   |  |

Is the property in an area where there is a steady demand for rented accommodation of this type?

| Yes |  | No |
|-----|--|----|
|-----|--|----|

#### **Declaration**

Signed Security Print Code [580287 = 7152 ]

Electronically signed by:-

Surveyor's name Alan E Cunningham

Professional qualifications BSc MRICS
Company name DM Hall LLP

Address 151 Kilmarnock Road, Glasgow, G41 3JF

Telephone 0141 636 4141
Fax 0141 632 5473
Report date 14th February 2020

# PROPERTY QUESTIONNAIRE





| Property address                          | FLAT 1,<br>34 SPEIRS WHARF,<br>GLASGOW,<br>G4 9TG |
|---|---|
|   |   |
| Seller(s)                                 | EMILY ALLAN                                       |
|   |   |
| Completion date of property questionnaire | 14/02/2020  |

#### **Note for sellers**

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

#### Information to be given to prospective buyer(s)

| 1. | Length of ownership   |
|----|---|
|    | How long have you owned the property? OCTOBER 2001  |
| 2. | Council tax   |
|    | Which Council Tax band is your property in? (Please circle)   |
|    | A B C D E F G H   |
| 3. | Parking   |
|    | What are the arrangements for parking at your property?   |
|    | (Please tick all that apply)  |
|    | • Garage  |
|    | Allocated parking space   |
|    | • Driveway  |
|    | Shared parking  |
|    | On street   |
|    | Resident permit   |
|    | Metered parking   |
|    | Other (please specify):  PARKING FOR RESIDENTS - FREE -NO ALLOCATED SPACE   |
| 4. | Conservation area   |
|    | Is your property in a designated Conservation Area (i.e. an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?  Yes / No / Don't know desirable to preserve or enhance)? |

| In community a listed Duilding on contained within one (i.e. a building   |  |  |  |  |  |
|---|--|--|--|--|--|
| Is your property a Listed Building, or contained within one (i.e. a building recognised and approved as being of special architectural or historical interest)?                           | Yes / <del>No</del>  |  |  |  |  |
| Alterations/additions/extensions  |  |  |  |  |  |
| (i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)? | Yes / <del>No</del>  |  |  |  |  |
| If you have answered yes, please describe below the changes which you have made:  |  |  |  |  |  |
| No structural works complete but moved two internal plasterboard walls to open out kitchen living space.  |  |  |  |  |  |
| (ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?   | <del>Yes</del> / No  |  |  |  |  |
| If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.                             |  |  |  |  |  |
| If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:                                      |  |  |  |  |  |
| not required as not structural  |  |  |  |  |  |
| Have you had replacement windows, doors, patio doors or double glazing installed in your property?  | <del>Yes</del> / No  |  |  |  |  |
| If you have answered yes, please answer the three questions below:  |  |  |  |  |  |
| (i) Were the replacements the same shape and type as the ones you replaced?   | Yes / No   |  |  |  |  |
| (ii) Did this work involve any changes to the window or door openings?  | Yes / Ne   |  |  |  |  |
| (iii) Please describe the changes made to the windows, doors or patio doors (with approximate dates when the work was completed):   |  |  |  |  |  |
| Please give any guarantees which you received for this work to your solicitor or ex   | state agent.   |  |  |  |  |
|   |  |  |  |  |  |
|   |  |  |  |  |  |
|   |  |  |  |  |  |
|   |  |  |  |  |  |
|   |  |  |  |  |  |
|   |  |  |  |  |  |
|   |  |  |  |  |  |
|   | Alterations/additions/extensions  (i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?  If you have answered yes, please describe below the changes which you have made:  No structural works complete but moved two internal plasterboard walls to open out kitchen living space.  (ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?  If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.  If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them: not required as not structural  Have you had replacement windows, doors, patio doors or double glazing installed in your property?  If you have answered yes, please answer the three questions below:  (i) Were the replacements the same shape and type as the ones you replaced?  (ii) Did this work involve any changes to the windows, doors or patio doors (with dates when the work was completed): |  |  |  |  |

| 7. | Central heating   |   |
|----|---|---|
| a. | Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property - the main living room, the bedroom(s), the hall and the bathroom). | Yes / <del>No</del> /<br><del>Partial</del> |
|    | If you have answered yes / partial - what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).  |   |
|    | Electric Storage Heaters - individually controlled  |   |
|    | If you have answered yes, please answer the three questions below:  |   |
| b. | When was your central heating system or partial central heating system installed?   | Beginning 2015                              |
| C. | Do you have a maintenance contract for the central heating system?  | <del>Yes</del> / No                         |
|    | If you have answered yes, please give details of the company with which you have a maintenance contract:  |   |
| d. | When was your maintenance agreement last renewed? (Please provide the month and year).  |   |
| 8. | Energy Performance Certificate  |   |
|    | Does your property have an Energy Performance Certificate which is less than 10 years old?  | <del>Yes</del> / No                         |
| 9. | Issues that may have affected your property   |   |
| a. | Has there been any storm, flood, fire or other structural damage to your property while you have owned it?  | <del>Yos</del> / No                         |
|    | If you have answered yes, is the damage the subject of any outstanding insurance claim?   | <del>Yes</del> / <del>No</del>              |
| b. | Are you aware of the existence of asbestos in your property?  | <del>Yes</del> / No                         |
|    | If you have answered yes, please give details:  |   |
|    |   |   |
|    |   |   |
|    |   |   |
|    |   |   |
|    |   |   |
|    |   |   |
|    |   |   |

### 10. **Services** a. Please tick which services are connected to your property and give details of the **Services** Connected **Supplier** Gas / liquid petroleum gas Water mains / I am not sure of the supplier private water supply **Electricity** Scottish Power Mains drainage I am not sure of supplier **Telephone** Originally BT - but not sure who now SKY Cable TV / satellite **Broadband** orignally BT - but not sure who now b. Is there a septic tank system at your property? Yes / No If you have answered yes, please answer the two questions below: (i) Do you have appropriate consents for the discharge from your septic tank? Yes / No / C. Don't know (ii) Do you have a maintenance contract for your septic tank? Yes / No d. If you have answered yes, please give details of the company with which you have a maintenance contract:

| 11. | Responsibilities for Shared or Common Areas   |  |
|-----|---|--|
| a.  | Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?   | Yes / <del>No</del> /<br><del>Don't Know</del> |
|     | If you have answered yes, please give details:  |  |
|     | There is a factor fee of £130 a month which cover building insurance/maintenance/repairs etc  |  |
| b.  | Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?  | Yes / No /<br>Not applicable                   |
|     | If you have answered yes, please give details:  |  |
|     | There is a factor fee of £130 a month which cover building insurance/maintenance/repairs etc  |  |
| c.  | Has there been any major repair or replacement of any part of the roof during the time you have owned the property?   | <del>Yes</del> / No                            |
| d.  | Do you have the right to walk over any of your neighbours' property - for example to put out your rubbish bin or to maintain your boundaries?   | <del>Yes</del> / No                            |
|     | If you have answered yes, please give details:  |  |
| e.  | As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?   | <del>Yes</del> / No                            |
|     | If you have answered yes, please give details:  |  |
| f.  | As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.) | <del>Yos</del> / No                            |
|     | If you have answered yes, please give details:  |  |
| 12. | Charges associated with your property   |  |
| a.  | Is there a factor or property manager for your property?  | Yes / <del>No</del>                            |
|     | If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:  |  |
|     | Speirs Wharf Proprietors Association 32 Speirs WHarf Glasgow G4 9TG committee@speirswharf.com   |  |
|     |   |  |
|     |   |  |
|     |   |  |
|     |   |  |
|     |   |  |
|     |   |  |

| b.  | Is there a common buildings insurance policy?  | Yes / <del>No</del> /<br><del>Don't Know</del> |
|-----|--|--|
|     | If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?   | Yes / <del>No</del> /<br><del>Don't Know</del> |
| C.  | Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.   |  |
| 13. | Specialist works   |  |
| a.  | As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?  | <del>Yes</del> / No                            |
|     | If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property:  |  |
| b.  | As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?   | <del>Yos</del> / No                            |
|     | If you have answered yes, please give details:   |  |
| C.  | If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?  | Yes / No                                       |
|     | If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. |  |
|     | Guarantees are held by:  |  |
|     |  |  |
|     |  |  |
|     |  |  |
|     |  |  |
|     |  |  |
|     |  |  |
|     |  |  |
|     |  |  |
|     |  |  |
|     |  |  |
|     |  |  |

| 14.   | Guarantees   |                      |           |               |  |      |                   |
|-------|--|----------------------|-----------|---------------|--|------|-------------------|
| a.    | Are there any guarantees or warranties for any of the following:                                       |                      |           |               |  |      |                   |
| (i)   | Electrical work  | No                   | Yes       | Don't<br>know | With<br>title<br>doods                         | Lost | Cannot<br>Answer* |
| (ii)  | Roofing  | Ne                   | Yos       | Don't<br>know | With<br>title<br>doods                         | Lost | Cannot<br>Answer* |
| (iii) | Central heating  | No                   | Yos       | Don't<br>know | With<br>title<br>doods                         | Lost | Cannot<br>Answor* |
| (iv)  | NHBC   | No                   | Yos       | Don't<br>know | With<br>title<br>doods                         | Lost | Cannot<br>Answer* |
| (v)   | Damp course  | Ne                   | Yes       | Don't<br>know | With<br>title<br>doods                         | Lost | Cannot<br>Answer* |
| (vi)  | Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy) | No                   | Yos       | Don't<br>know | With<br>title<br>doods                         | Lost | Cannot<br>Answer* |
| b.    | If you have answered 'yes' or 'with title deed<br>or installations to which the guarantee(s) rela      | ls', pleas<br>te(s): | e give de | etails of t   | he work  |      |                   |
|       | electrical test and certificates have been kept up   | to date.             |           |               |  |      |                   |
| c.    | Are there any outstanding claims under any o   | of the gua           | arantees  | listed abo    | ove?   | You  | ·/ No             |
|       | If you have answered yes, please give details  | :                    |           |               |  |      |                   |
| 15.   | Boundaries   |                      |           |               |  |      |                   |
|       | So far as you are aware, has any boundary of your property been moved in the last 10 years?            |                      |           |               | <del>Yos</del> / No /<br><del>Don't know</del> |      |                   |
|       | If you have answered yes, please give details:   |                      |           |               |  |      |                   |
|       |  |                      |           |               |  |      |                   |
|       |  |                      |           |               |  |      |                   |
|       |  |                      |           |               |  |      |                   |
|       |  |                      |           |               |  |      |                   |
|       |  |                      |           |               |  |      |                   |
|       |  |                      |           |               |  |      |                   |
|       |  |                      |           |               |  |      |                   |
|       |  |                      |           |               |  |      |                   |
|       |  |                      |           |               |  |      |                   |

| 16. | Notices that affect your property   |  |
|-----|---|--|
|     | In the past 3 years have you ever received a notice:  |  |
| a.  | advising that the owner of a neighbouring property has made a planning application?   | Yes / No /<br>Den't know                       |
| b.  | that affects your property in some other way?   | <del>Yes</del> / No /<br><del>Don't know</del> |
| C.  | that requires you to do any maintenance, repairs or improvements to your property?  | <del>Yes</del> / No /<br><del>Den't knew</del> |
|     | If you have answered yes to any of a-c above, please give the notices to your so agent, including any notices which arrive at any time before the date of entry of t your property. | olicitor or estate<br>he purchaser of          |

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

| Signature(s): |  |  |  |
|---------------|--|--|--|
|               |  |  |  |
|               |  |  |  |
| Date:         |  |  |  |

# **DM Hall Offices**

Aberdeen 01224 594172

Ayr 01292 286974

Cumbernauld 01236 618900

Cupar 01334 844826

Dumfries 01387 254318

Dundee 01382 873100

**Dunfermline** 01383 621262

Edinburgh 0131 477 6000

Elgin 01343 548501

Falkirk 01324 628321 Galashiels Livingston 01896 752009 01506 490404

Glasgow (North) Mus 0141 332 8615 013

Glasgow (South) 0141 636 4141

Hamilton 01698 284939

Inverness 01463 241077

Inverurie 01467 624393

01294 311070

Irvine

Kirkcaldy 01592 598200

Musselburgh

0131 665 6782

Oban

01631 564225

Paisley

0141 887 7700

Perth

01738 562100

Peterhead 01779 470220

Stirling 01786 475785

DMHALL.CO.UK