



the home report

survey report on:

Property address	The Coach House St Germains LONGNIDDRY EH32 0PQ	
Customer	Mr and Mrs Penman	
Customer address	The Coach House St Germains LONGNIDDRY EH32 0PQ	
Prepared by	ALLIED SURVEYORS SCOTLAND PLC	
Date of inspection	10th July 2020	



PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.



The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in the expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:-

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report ² will be from information contained in the Report and the generic Mortgage Valuation Report.

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller:
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2. Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3. Category 1: No immediate action or repair is needed.

WARNING:

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value, the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The property forms a detached house over two storeys.
Accommodation	Ground Floor: Hall, Drawing Room, Sun Room, Family Room, Dining Hall, Kitchen, Bedroom and WC Apartment First Floor: Upper Hall, Three Bedrooms, En-Suite Bathroom (No WC), Family Bathroom (with WC) and WC Apartment
Gross internal floor area (m²)	264 approx.
Neighbourhood and location	The property is situated within a semi rural setting to the west of Longniddry. There are adequate amenities available within Longniddry including public transport links.
Age	Originally built circa 1775. The side extensions were added at a later date but can be considered longstanding.
Weather	Dry and sunny.
Chimney stacks	Visually inspected with the aid of binoculars where appropriate. The chimney stack was seen to be of concrete blockwork.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate. Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally. Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space

may be taken by other means if the Surveyor deems it safe and reasonable to do so.

The roof over the original part of the property is pitched and hipped and has a timber frame. Attached to the frame is timber sarking and this has been overlaid with roofing slates. We were unable to ascertain whether underfelt has been utilised.

Only a limited head and shoulders inspection of the void was possible due to the presence of insulation and a lack of flooring.

Not all of the pitched roof coverings were visible, particularly to the east and west facing pitches on the north elevation.

The roofs over the side extensions are felt covered flat platforms with the majority being treated with a reflective paint.

Rainwater fittings

Visually inspected with the aid of binoculars where appropriate.

The rainwater fittings are of cast iron.

Main walls

Visually inspected with the aid of binoculars where appropriate.

Foundations and concealed parts were not exposed or inspected.

The walls to the original part of the property are of solid stonework.

The walls to the extensions appear to be primarily cavity masonry with stone and concrete blockwork outer leaves, although it is likely the north wall of the kitchen is of solid stone.

Windows, external doors and joinery

Internal and external doors were opened and closed where keys were available.

Random windows were opened and closed where possible.

Doors and windows were not forced open.

The property is predominantly single glazed. Single glazed windows are in 'sash and case' and 'casement' styles and are encased within timber.

Double glazed windows are in a 'casement' style and are encased within PVC.

There is a timber external door and two PVC external doors, both of which have double glazed panels.

External decorations	Visually inspected.
	The external timberwork and rainwater goods have been painted.
	The external timberwork and rainwater goods have been painted.
Conservatories / porches	There are none.
Communal areas	There are no internal communal areas.
Garages and permanent outbuildings	Visually inspected.
	The property has a double car detached garage which has been constructed in concrete blockwork and has a metal roof. The garage has two up and over doors to the front and an access door to the side.
	Attached to the east end of the property is a garden store. This has been constructed in stone, brickwork and concrete blockwork and has a flat felt roof.
	The property also has a timber shed and a greenhouse.
	The internal inspections of the garage and outbuildings were limited due to the presence of stored items.
Outside areas and boundaries	Visually inspected.
	The property has private garden ground to three sides and a chicken coop behind the garage. Boundaries are formed in hedging, brick walls and another property.
Ceilings	Visually inspected from floor level.
	The ceilings appear to be a mix of lath and plaster and plasterboard.
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	The walls are of plasterboard or have been hard plaster lined.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
	The flooring within the property is a mixture of solid and suspended


	timber.
	No subfloor inspection was possible due to a lack of access.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	The internal joinery within the property is of painted or treated timberwork.
	The kitchen houses a range of modern wall and floor mounted units.
Chimney breasts and fireplaces	Visually inspected.
	No testing of the flues or fittings was carried out.
	There is an open fireplace within the sitting room.
Internal decorations	Visually inspected.
Internal decorations	
	The walls and ceilings within the property have been papered and/or painted.
Cellars	There are no cellars.
	There are the contains.
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. The property is connected to the mains electricity supply. There are fuses and an electricity meter in a cupboard off the kitchen and a further fuse board within the inner hall.
Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and
	meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	The property is not connected to the mains gas supply.
	The property has propane gas tanks for the kitchen cooker/hob.

Water, plumbing, bathroom fittings Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation. No tests whatsoever were carried out to the system or appliances. The property is connected to the mains water supply. Visible pipework was seen to be of copper or PVC. There is a PVC cold tank within the roof void. The fitments within the bathroom, en-suite and WC apartment at first floor level are rather dated. The WC and basin within the WC apartment at ground floor level are relatively modern. Heating and hot water Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances. The property has full oil fired central heating. A Worcester Greenstar Danesmoor boiler, located within a cupboard off the kitchen, serves panel radiators throughout the property and, in conjunction with an immersion system, supplies hot water. A lagged hot water cylinder is located within the same cupboard. Drainage Drainage covers etc. were not lifted. Neither drains nor drainage systems were tested. The property is connected to a shared septic tank. Fire, smoke and burglar alarms Visually inspected. No tests whatsoever were carried out to the system or appliances. Smoke and burglar alarms were noted. For flats / maisonettes Any additional limits to inspection Only the subject flat and internal communal areas giving access to the flat were inspected. If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation. The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.

The inspection was limited due to fitted floor coverings, stored

personal items and furnishings.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1 Chimney pots
- 2 Coping stone
- 3) Chimney head
- 4) Flashing
- (5) Ridge ventilation
- 6) Ridge board
- 7) Slates / tiles
- (8) Valley guttering
- 9 Dormer projection
- (10) Dormer flashing
- 11) Dormer cheeks
- (12) Sarking
- 13) Roof felt
- (14) Trusses
- 15) Collar
- (16) Insulation
- 17) Parapet gutter
- 18) Eaves guttering
- 19) Rainwater downpipe
- Verge boards /skews
- (21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- co Latir/ plaster
- (24) Chimney breast
- 25) Window pointing
- 26 Window sills
- (27) Rendering
- (28) Brickwork / pointing
- 29) Bay window projection
- (30) Lintels
- (31) Cavity walls / wall ties
- 32) Subfloor ventilator
- 33) Damp proof course
- (34) Base course
- 35) Foundations
- 36) Solum
- 37) Floor joists
- 38) Floorboards
- 9) Water tank
- 40) Hot water tank

2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	

Structural movemen	nt
Repair category	1
Notes	There was no visible evidence of any significant structural movement affecting the property.

Dampness, rot and infestation	
Repair category	2
Notes	Evidence of woodworm was noted within the roof void and it would appear this is currently active.
	Raised moisture meter readings were obtained in the sitting room and dining hall.
	We understand the owners are going to obtain specialist advice with regards to these items.

Chimney stacks	
Repair category	1
Notes	No significant defects were noted.

Roofing including roof space	
Repair category	2
Notes	With regards to the original roof a small number of cracked slates were evident. With regards to the flat roofs ponding was evident to the sun room roof and cracked and rucked felt was evident to the roofs over the kitchen and family room. The sun room roof has been patched up in the past. Felt roofs have a limited life span and can fail without warning.

Rainwater fittings	
Repair category	1
Notes	A few spots of corrosion were noted to the rainwater goods.

Main walls	
Repair category	1
Notes	A few patches of cracked or weathered stonework was evident, although this is not considered inconsistent with the age of the property.

Windows, external doors and joinery	
Repair category	2
Notes	Two of the window cills at first floor level were noted to be softening at the time of our inspection, however, we have been notified that these have since been replaced.
	There is a blow seal to a window within the sun room. We understand a new window has been ordered.
	The skylight above the WC apartment at first floor level is corroding.

External decorations	
Repair category	2
Notes	The external paintwork is cracked and weathered in places, particularly to some of the first floor window frames and cills.

Conservatories/porches	
Repair category	-
Notes	N/A

Communal areas	
Repair category	-
Notes	N/A

Garages and permanent outbuildings	
Repair category	1
Notes	The external paintwork to the garage is weathered in places and there is rather excessive vegetation growth.
	The greenhouse is in a weathered condition.

Outside areas and boundaries	
Repair category	1
Notes	No significant defects were noted.

Ceilings	
Repair category	1
Notes	Some plaster cracking was noted.

Internal walls	
Repair category	1
Notes	Some plaster cracking was noted.

Floors including sub-floors	
Repair category	1
Notes	The flooring was noted to be slightly uneven in places.

Internal joinery and kitchen fittings	
Repair category	1
Notes	No significant defects were noted.

Chimney breasts and fireplaces	
Repair category	1
Notes	No significant defects were noted.
	Chimney breast should be checked and swept before use.

Internal decorations	
Repair category	1
Notes	No significant defects were noted.

Cellars	
Repair category	-
Notes	N/A

Electricity	
Repair category	2
Notes	The property is served by dated fuse boards instead of a more modern circuit breaker system. Cut wiring was noted within the boiler cupboard and in the high level hall cupboard containing a fuse board. It is unlikely this wiring is connected to a power supply but we would recommend it be checked.

Gas	
Repair category	1
Notes	No significant defects were noted to the private propane supply.

Water, plumbing and bathroom fittings			
Repair category	2		
Notes	The fitments within the first floor bathrooms and WC apartment are rather dated and would now benefit from replacement.		

Heating and hot water		
Repair category 1		
Notes	tes The radiators are dated and some have cracked paint.	

Drainage	
Repair category	1
Notes	No significant defects were noted.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	2
Chimney stacks	1
Roofing including roof space	2
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	2
External decorations	2
Conservatories/porches	-
Communal areas	-
Garages and permanent outbuildings	1
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	-
Electricity	2
Gas	1
Water, plumbing and bathroom fittings	2
Heating and hot water	1
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground and First Floors.
2. Are there three steps or fewer to a main entrance door of the property?	Yes X No
3. Is there a lift to the main entrance door of the property?	Yes No X
4. Are all door openings greater than 750mm?	Yes No X
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No
6. Is there a toilet on the same level as a bedroom?	Yes X No
7. Are all rooms on the same level with no internal steps or stairs?	Yes No X
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

No recent alterations noted.

The property is Listed.

Responsibility for any communal areas should be ascertained.

The property has a right of access over land under separate ownership.

The garage is on a separate site.

The property is connected to a private septic tank. The Conveyancer should ascertain that all appropriate legal rights exist for the presence and future maintenance and/or renewal of all elements of the drainage installation which are located outwith the site boundaries, and that it is registered with SEPA.

Estimated reinstatement cost for insurance purposes

The estimated reinstatement cost for insurance purposes is £950,000 (Nine Hundred and Fifty Thousand Pounds Sterling).

This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction, on a reinstatement basis, assuming reconstruction of the property in its existing design and materials. Finishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during reconstruction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers is advised. The figure should be reviewed annually and in light of any future alterations or additions.

Valuation and market comments

The market value of the property described in the report is £625,000 (Six Hundred and Twenty Five Thousand Pounds Sterling).

This figure assumes vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights.

Property market activity has been impacted due to the current response to Covid-19. This has resulted in an unprecedented set of circumstances on which to make a valuation judgement. The advice is therefore reported on the basis of "material valuation uncertainty" as per the RICS Red Book Global definition. Consequently, less certainty can be attached to the valuation than would otherwise be the case. It is recommended that the valuation of this property is kept under frequent review as more market evidence becomes available.

Signed	Security Print Code [414585 = 1428] Electronically signed
Report author	Simon Breeze

Company name	ALLIED SURVEYORS SCOTLAND PLC
Address	21 Church Street, Haddington, EH41 3EX
Date of report	20th July 2020



Property Address	
Address Seller's Name Date of Inspection	The Coach House, St Germains, LONGNIDDRY, EH32 0PQ Mr and Mrs Penman 10th July 2020
Property Details	
Property Type	X House Bungalow Purpose built maisonette Converted maisonette Purpose built flat Converted flat Tenement flat Flat over non-residential use Other (specify in General Remarks)
Property Style	X Detached Semi detached Mid terrace End terrace Back to back High rise block Low rise block Other (specify in General Remarks)
Does the surveyor be e.g. local authority, m	lieve that the property was built for the public sector, Yes X No illitary, police?
Flats/Maisonettes onl	No. of units in block
Approximate Year of	Construction 1775
Tenure	
X Absolute Ownership	Leasehold Ground rent £ Unexpired years
Accommodation	
Number of Rooms	3 Living room(s) 4 Bedroom(s) 1 Kitchen(s) 2 Bathroom(s) 3 WC(s) 0 Other (Specify in General remarks)
Gross Floor Area (exc	cluding garages and outbuildings) 264 m² (Internal) m² (External)
Residential Element (greater than 40%) X Yes No
Garage / Parking /	Outbuildings
Single garage Available on site? Permanent outbuildin	X Double garage □ Parking space □ No garage / garage space / parking space □ Yes X No gs: □ No garage / garage space / parking space
Garden store, green	house and timber shed.

Construction							
Walls	Brick	X Stone	Concre	te Timber frar	ne Otl	ner (specify in Ger	neral Remarks)
Roof	Tile	X Slate	Asphal	Felt	Oti	ner (specify in Ger	neral Remarks)
Special Risks							
Has the property	suffered struc	ctural movem	ent?			Yes	X No
If Yes, is this rece	ent or progres	sive?				Yes	No
Is there evidence, immediate vicinity		eason to anti	cipate subsider	ice, heave, lands	ip or flood in t	he Yes	X No
If Yes to any of th	e above, pro	vide details ir	n General Rem	arks.			
Service Connec	ctions						
Based on visual ir of the supply in G			vices appear to	be non-mains, pl	ease commer	it on the type a	and location
Drainage	Mains	X Private	None	Wate	er X Mains	Private	None
Electricity	X Mains	Private	None	Gas	Mains	X Private	None
Central Heating	X Yes	Partial	None				
Brief description of	of Central Hea	ating:					
Oil fired boiler se	erving panel r	adiators.					
Site							
Apparent legal iss	sues to be ve	rified by the o	convevancer. I	Please provide a l	orief description	n in General R	temarks.
X Rights of way	X Shared dri	•	_	her amenities on sepa	<u> </u>	nared service conr	
Ill-defined boundar	ries	Agricu	ultural land include	•		ther (specify in Ge	
Location							
Residential suburb	Re	esidential within	town / city	/lixed residential / con	nmercial M	ainly commercial	
Commuter village	Re	emote village	I	solated rural property	X O	ther (specify in Ge	neral Remarks)
Planning Issues	S						
Has the property I	been extende	ed / converte	d / altered?	Yes X No			
If Yes provide det	ails in Gener	al Remarks.					
Roads							
X Made up road	Unmade roa	ad Partl	y completed new r	pad Pedestri	an access only	Adopted	Unadopted

General Remarks
The property is situated within a semi rural setting to the west of Longniddry. There are adequate amenities available within Longniddry including public transport links.
The property was found to be in a general condition consistent with age and construction. Minor defects were noted but these should be capable of remedy in the course of routing maintenance. In addition to these minor defects, dampness and woodworm were noted and these should be eliminated.
No recent alterations noted.
The property is Listed.
Responsibility for any communal areas should be ascertained.
The property has a right of access over land under separate ownership.
The garage is on a separate site.
Property market activity has been impacted due to the current response to Covid-19. This has resulted in an unprecedented set of circumstances on which to make a valuation judgement. The advice is therefore reported on the basis of "material valuation uncertainty" as per the RICS Red Book Global definition. Consequently, less certainty can be attached to the valuation than would otherwise be the case. It is recommended that the valuation of this property is kept under frequent review as more market evidence becomes available.
Essential Repairs
Investigation and elimination of dampness.

Estimated cost of essential repairs £	Retention recommended? Tes	X No	Amount £	

Comment on Mortgageal	bility	
The property provides suit	able security for lending purposes, subject to individual lenders' requirem	ents.
Valuations		
Market value in present con Market value on completion Insurance reinstatement val (to include the cost of total r Is a reinspection necessary	of essential repairs lue rebuilding, site clearance, professional fees, ancillary charges plus VAT)	£ 625,000 £ 950,000
Buy To Let Cases		
month Short Assured Tenar		£
Is the property in an area w	here there is a steady demand for rented accommodation of this type?	Yes No
Declaration		
Signed	Security Print Code [414585 = 1428] Electronically signed by:-	
Surveyor's name	Simon Breeze	
Professional qualifications	MA (Hons) MSc MRICS	
Company name	ALLIED SURVEYORS SCOTLAND PLC 31 Church Street Haddington EH41 3EV	
Address	21 Church Street, Haddington, EH41 3EX	
Telephone	01620 825585	
Fax Report date	20th July 2020	

Energy Performance Certificate (EPC)

Dwellings

Scotland

The Coach House, St Germains, Longniddry, EH32 0PQ

Dwelling type: Detached house Date of assessment: 10 July 2020 Date of certificate: 15 July 2020 **Total floor area:** 264 m²

Primary Energy Indicator: 293 kWh/m²/year

Reference number: 6510-2123-1530-2250-6296 Type of assessment: RdSAP, existing dwelling

Approved Organisation: **Elmhurst**


Main heating and fuel: Boiler and radiators, oil

You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£10,062	See your recommendations
Over 3 years you could save*	£4,764	report for more information

^{*} based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is band F (35). The average rating for EPCs in Scotland is band D (61).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO₂) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band F (30)**. The average rating for EPCs in Scotland is band D (59).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Increase loft insulation to 270 mm	£100 - £350	£303.00
2 Flat roof or sloping ceiling insulation	£850 - £1,500	£357.00
3 Cavity wall insulation	£500 - £1,500	£588.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE **DWELLING AND NOT BE REMOVED UNLESS IT IS** REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Sandstone or limestone, as built, no insulation (assumed)	***	***
	Cavity wall, as built, partial insulation (assumed)	***	★★★☆☆
Roof	Pitched, 50 mm loft insulation Flat, limited insulation (assumed)	★★☆☆☆ ★★☆☆☆	***** ***
Floor	Suspended, no insulation (assumed) Solid, no insulation (assumed)	_ _	_ _
Windows	Some double glazing	***	***
Main heating	Boiler and radiators, oil	★★★ ☆☆	****
Main heating controls	Programmer, TRVs and bypass	★★★ ☆☆	***
Secondary heating	Room heaters, dual fuel (mineral and wood)	_	_
Hot water	From main system	★★★☆☆	***
Lighting	Low energy lighting in 67% of fixed outlets	★★★★ ☆	★★★★ ☆

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO_2 emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 75 kg $CO_2/m^2/yr$.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 20 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 10.9 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£8,988 over 3 years	£4,467 over 3 years	
Hot water	£549 over 3 years	£297 over 3 years	You could
Lighting	£525 over 3 years	£534 over 3 years	save £4,764
Totals	£10,062	£5,298	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Do		mended measures Indicative cost Typical saving		Rating after	improvement
Re	commended measures	indicative cost	per year	Energy	Environment
1	Increase loft insulation to 270 mm	£100 - £350	£101	F 37	F 31
2	Flat roof or sloping ceiling insulation	£850 - £1,500	£119	E 39	F 33
3	Cavity wall insulation	£500 - £1,500	£196	E 42	F 36
4	Internal or external wall insulation	£4,000 - £14,000	£512	E 53	E 45
5	Floor insulation (suspended floor)	£800 - £1,200	£85	D 55	(E 46
6	Floor insulation (solid floor)	£4,000 - £6,000	£157	D 58	(E 49
7	Draughtproofing	£80 - £120	£107	D 60	E 51
8	Upgrade heating controls	£350 - £450	£93	D 62	E 53
9	Solar water heating	£4,000 - £6,000	£60	D 63	D 55
10	Replace single glazed windows with low- E double glazed windows	£3,300 - £6,500	£159	D 66	D 59
11	Solar photovoltaic panels, 2.5 kWp	£3,500 - £5,500	£326	C 71	D 63

Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

External insulation with cavity wall insulation

Choosing the right improvement package



For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Loft insulation

Loft insulation laid in the loft space or between roof rafters to a depth of at least 270 mm will significantly reduce heat loss through the roof; this will improve levels of comfort, reduce energy use and lower fuel bills. Insulation should not be placed below any cold water storage tank, any such tank should also be insulated on its sides and top, and there should be boarding on battens over the insulation to provide safe access between the loft hatch and the cold water tank. The insulation can be installed by professional contractors but also by a capable DIY enthusiast. Loose granules may be used instead of insulation quilt; this form of loft insulation can be blown into place and can be useful where access is difficult. The loft space must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about loft insulation and details of local contractors can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk).

2 Flat roof or sloping ceiling insulation

Insulating a flat roof or sloping ceiling will significantly reduce heat loss through the roof; this will improve levels of comfort, reduce energy use and lower fuel bills. Insulation can be placed on top of the roof under the waterproof membrane and should particularly be considered when the waterproofing needs to be replaced. Further information about roof insulation and details of local contractors can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). Building regulations generally apply to this work so it is best to check with your local authority building standards department.

3 Cavity wall insulation

Cavity wall insulation, to fill the gap between the inner and outer layers of external walls with an insulating material, reduces heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. The insulation material is pumped into the gap through small holes that are drilled into the outer walls, and the holes are made good afterwards. As specialist machinery is used to fill the cavity, a professional installation company should carry out this work, and they should carry out a thorough survey before commencing work to ensure that this type of insulation is suitable for this home and its exposure. They should also provide a guarantee for the work and handle any building standards issues. Further information about cavity wall insulation and details of local installers can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk).

4 Internal or external wall insulation

Internal or external wall insulation involves adding a layer of insulation to either the inside or the outside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. External solid wall insulation is the application of an insulant and a weather-protective finish to the outside of the wall. This may improve the look of the home, particularly where existing brickwork or rendering is poor, and will provide long-lasting weather protection. Further information can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). It should be noted that a building warrant is required for the installation of external wall insulation. Planning permission may also be required and that building regulations apply to external insulation so it is best to check with your local authority on both issues.

5 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

6 Floor insulation (solid floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Insulating solid floors can present challenges; insulation laid on top of existing solid floors may impact on existing doors and finishes whilst lifting of a solid floor to insert insulation below will require consideration of the potential effect on both structural stability and damp proofing. It is advised to seek advice from a Chartered Structural Engineer or a registered Architect about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work and may also require a building warrant so it is best to check with your local authority building standards department.

7 Draughtproofing

Fitting draughtproofing, strips of insulation around windows and doors, will improve the comfort in the home. A contractor can be employed but draughtproofing can be installed by a competent DIY enthusiast.

8 Heating controls (room thermostat)

The heating system should have a room thermostat to enable the boiler to switch off when no heat is required. A competent heating engineer should be asked to do this work. Insist that the thermostat switches off the boiler as well as the pump and that the thermostatic radiator valve is removed from any radiator in the same room as the thermostat. Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

9 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

10 Double glazed windows

Double glazing is the term given to a system where two panes of glass are made up into a sealed unit. Replacing existing single-glazed windows with double-glazed windows will improve comfort in the home by reducing draughts and cold spots near windows. Double-glazed windows may also reduce noise, improve security and combat problems with condensation. Building regulations apply to this work and planning permission may also be required, so it is best to check with your local authority on what standards need to be met. A building warrant is not required if the windows comply with the current requirements.

11 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	47,330	(1,629)	(3,111)	(8,067)
Water heating (kWh per year)	3,275			

Addendum

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Simon Breeze
Assessor membership number: EES/008265

Company name/trading name: Allied Surveyors Scotland Plc

Address: 21 Church Street Haddington

EH41 3EX 01620 825585

Phone number: 01620 825585

Email address: haddington@alliedsurveyors.com

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greeners cotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT



Property Questionnaire

PROPERTY ADDRESS:

THE COMPH HOUSE

ST GERMAINS

LONGNIANNI

EHJZ SPZ

SELLER(S):

JIM & SOSAN VENMAN

COMPLETION DATE OF PROPERTY QUESTIONNAIRE:

9th July 2020

PROPERTY QUESTIONNAIRE

NOTE FOR SELLERS

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the Date of Entry for the sale of your house, tell your solicitor or estate agent immediately.

PROPERTY QUESTIONNAIRE Information to be given to prospective buyer(s)

	bish Council Tax band is your property in?	
Wi	high Council Tay band is your property in?	
	hich Council Tax band is your property in? A B C D E F G H	Н
.Pa	arking	
WI	hat are the arrangements for parking at your property?	
(P	lease indicate all that apply)	

	Allocated parking space	1
	• Driveway	V
	Shared parking	,
	• On street	
	· Resident permit	
	Metered parking	
	Other (please specify):	
	Control of the contro	
1.	Conservation Area	
1.	Is your property in a designated Conservation Area (i.e. an area of special architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance)?	on't
	Is your property in a designated Conservation Area (i.e. an area of special architectural or historic interest, the character or appearance of which it is desirable to	on't
	Is your property in a designated Conservation Area (i.e. an area of special architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance)?	on't know
5.	Is your property in a designated Conservation Area (i.e. an area of special architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance)? Listed Buildings Is your property a Listed Building, or contained within one (i.e. a building recognised and approved as being	on't know No
5.	Is your property in a designated Conservation Area (i.e. an area of special architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance)? Listed Buildings Is your property a Listed Building, or contained within one (i.e. a building recognised and approved as being of special architectural or historical interest)? Alterations / additions / extensions (i) During your time in the property, have you carried	on't know No Yes/No
5.	Is your property in a designated Conservation Area (i.e. an area of special architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance)? Listed Buildings Is your property a Listed Building, or contained within one (i.e. a building recognised and approved as being of special architectural or historical interest)? Alterations / additions / extensions (i) During your time in the property, have you	on't know

Please work to	give any guarantees whi	ich you received for this agent.
Centra	heating	

		Name and Address of the Owner, where the Parket of the Owner, where the Parket of the Owner, where the Owner, which is the Owner,
_		
a.	Is there a central heating system in your property?	Yes/No
	(Note: a partial central heating system is one which does not heat all the main rooms of the property - the	Partial
	main living room, the bedroom(s), the hall and the	1/63
	bathroom).	
	If you have answered yes/partial - what kind of central	
	heating is there?	BIL FIRE!
	(Examples: gas-fired, solid fuel, electric storage heating, gas warm air.)	
	If you have answered yes, please answer the 3 questions below:	
b.	When was your central heating system or partial	
	central heating system installed?	
		1986
		1986
C.	Do you have a maintenance contract for the central heating system?	Yes/No
	If you have answered yes, please give details of the	100
	company with which you have a maintenance agreement:	and the second
	6, A. Penny + Sod	- 1
	LINKS CSTTMEC.	
	TUMPLAR PLACE,	
	GULLANE	5.05
d.	When was your maintenance agreement last renewed? (Please provide the month and year).	
	(i case provide the month and year).	
		111/21/22
	191 101	May 2000

8.	Energy Performance Cert	ificate		
	Does your property have an Energy Performance Certificate which is less than 10 years old?		Yes/No	
9.	Issues that may have affe	Issues that may have affected your property		
a.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?		Yes/No	
	If you have answered yes, is the damage the subject of any outstanding insurance claim?			Yes/No
b.	Are you aware of the exis property?	tence of asbestos	in your	Yes/No
	If you have answered yes, please give details:			
	Services			
10	Services			
	Services Please tick which service property and give details		your	
	Please tick which service		your	
	Please tick which service property and give details	of the supplier:	Supplier 1-204AS BY 4 SUMMATE	STATION
	Please tick which service property and give details Services Gas / liquid petroleum	Connected PROPAGE FOR	Supplier	STATION
	Please tick which service property and give details Services Gas / liquid petroleum gas Water mains / private	Connected PROPAGE FOR COOKER	Supplier 1-204AS BY 4 SUMMATE	STATION
	Please tick which service property and give details Services Gas / liquid petroleum gas Water mains / private water supply	Of the supplier: Connected PROPAGE FOR COOKER	Supplier FLOCAS BY H SHOWATE LEDINBURG SCOTTISH POWER	STATION
	Please tick which service property and give details Services Gas / liquid petroleum gas Water mains / private water supply Electricity	Of the supplier: Connected PROPANC FOR COOKER MAINS	Supplier FLOCAS BY H SHOWATE LEDINBURG SCOTTISH POWER	STATION
10 a.	Please tick which service property and give details Services Gas / liquid petroleum gas Water mains / private water supply Electricity Mains drainage	of the supplier: Connected PROPADE FOR COOKER WANIES	Supplier FLOCAS BY H SILVENDED LEDINBURD SCOTTISH POWER	STATION

D.	Is there a septic tank system at your property?	Yes/No
	If you have answered yes, please answer the two questions below:	1/25
	from your septic tank?	Don't Know
d.	Do you have a maintenance contract for your septic tank?	Yes/No
	If you have answered yes, please give details of the company with which you have a maintenance contract:	

a.	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area? If you have answered yes, please give details:	Yes/No/ Don't Know	
b.	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas? If you have answered yes, please give details:	Yes/No/ Not applicable	241
c.	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	Yes/No	

	Do you have the right to walk over any of your neighbours' property - for example to put out your rubbish bin or to maintain your boundaries?	Yes/No
	If you have answered yes, please give details: ACLUST TO BINS. ACLUST TO GARAGE.	
	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries? If you have answered yes, please give details:	Yes/No No
f.	As far as you are aware, is there a Public Right of Way across any part of your property? (A Public Right of Way is a way over which the public has a right to pass, whether or not the land is privately-owned.) If you have answered yes, please give details:	Yes/No No
12.	Charges associated with your property	
a.	Is there a factor or property manager for your property? If you have answered yes, please provide the name and address and give details of any deposit held and approximate charges:	Yes/No
b.	Is there a common buildings insurance policy?	Yes/No/ Don't No know

	If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?	Yes/No/ Don't know
C.	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, e.g. to a Residents' Association, or maintenance or stair fund. Supric Thuik CNARCES SHARED WITH MISSER MICHAEL WITH MISSER MINE HOUSEROWS.	
13.	Specialist Works	
	As far as you are aware has treatment of de-	\/ (A)
a.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property? If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property Sich Bison	Yes/No

c. If you have answered yes to 13(a) or (b), do Yes/No you have any guarantees relating to this work? If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. Guarantees are held by: 14. Guarantees a. Are there any guarantees or warranties for any of the following: (i) Electrical work No Yes Don't With title Lost No Know deeds No Yes Don't With title Lost (ii) Roofing NA Know deeds (iii) Central heating **No Yes** Don't With title Lost No know deeds No Yes With title Lost (iv)NHBC Don't No deeds know **No Yes** With title Lost Don't (v) Damp course No deeds know (vi) Any other work or **No Yes** With title Lost Don't installations? deeds know (for example, cavity wall insulation, underpinning, No indemnity policy) b. If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):

C.	Are there any outstanding claims under any of the guarantees listed above? If you have answered yes, please give details:	Yes/No	
15	Boundaries	appul.	ugië
	So far as you are aware, has any boundary of your property been moved in the last 10 years? If you have answered yes, please give details:	Yes/No/ Don't Know	is C
16.	Notices that affect your property		
	In the past 3 years have you ever received a notice:		
a.	advising that the owner of a neighbouring property has made a planning application?	Yes/No/ Don't know	No
	that affects your property in some other way?	Yes/No/ Don't know	No
	that requires you to do any maintenance, repairs or improvements to your property?	Yes/No/ Don't know	No
	If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchase of your property.		

Declaration by the seller(s)/or other authorised body or person(s):

I / We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s):

Lusan Cenman

Date: 9th July 2000

